

Baofeng UV-82 transceiver has intermittent power

Sept 7, 2015

Symptom:

The radio reboots whenever the volume control or microphone connector is jiggled slightly.

Solution:

When you remove the battery, you will see a pair of gold plated terminals on the main unit, which contact the respective contacts on the battery.

One of these was loose - 1/4 turn tighten on the mounting screw fixed it !!

See photo:



Don Dorward VA3DDN